To begin:
Step 1. Select Metal in column B
Step 2. Select from dropdown in column C (wrong combination will trigger RED color)
Step 3. If dropdown selection is "Smelter Not Listed" complete columns D & E
Step 4. Enter all available smelter information in columns H thru P
Mandatory fields are noted with an asterisk (*).

cfsi
An initiative of the EICC and GeSI

© 2015 Conflict-Free Sourcing Initiative. All rights reserved.

Metal (*)	Smelter Reference List (*)	Smelter Name (*)	Smelter Country (*)	Smelter Identification	Source of Smelter Identification Number	Smelter Street	Smelter City	Smelter Facility Location: State / Province
Gold	Metalor USA Refining Corporation	Metalor USA Refining Corporation	UNITED STATES	CID001157	CFSI		North Attleboro	Massachusetts
Tin	Bangka Tin,Mentok,PT Timah (Persero) TBK	PT Timah (Persero), Tbk	INDONESIA	CID001482	CFSI			
Tin	Minsur	Minsur	PERU	CID001182	CFSI		Paracas	Ica
Tin	PT Indora Ermulti Logam Industri	PT Bukit Timah	INDONESIA	CID001428	CFSI			
Tin	PT TAMBANG TIMAH (KUNDUR)	PT Tambang Timah	INDONESIA	CID001477	CFSI			
Tin	Thaisarco	Thaisarco	THAILAND	CID001898	CFSI		Amphur Muang	Phuket
Tin	EM Vinto	EM Vinto	BOLIVIA	CID000438	CFSI		Oruro	Cercado
Tin	PT Timah	PT Timah (Persero), Tbk	INDONESIA	CID001482	CFSI		Mentok	Bangka
Tin	Malaysia Smelting Corporation (MSC)	Malaysia Smelting Corporation (MSC)	MALAYSIA	CID001105	CFSI		Butterworth	Penang
Tin	Mineração Taboca S.A.	Mineração Taboca S.A.	BRAZIL	CID001173	CFSI		Bairro Guarapiranga	São Paulo
Tin	OMSA	OMSA	BOLIVIA	CID001337	CFSI		Oruro	Cercado
Tin	Yunnan Tin Company, Ltd.	Yunnan Tin Company, Ltd.	CHINA	CID002180	CFSI		Geiju	Yunnan
Tin	Cooper Santa	Cooper Santa	BRAZIL	CID000295	CFSI		Ariquemes	Rondonia
Tin	Metallo Chimique	Metallo Chimique	BELGIUM	CID001143	CFSI			
Tin	PT Refined Bangka TIN (RBT)	PT REFINED BANGKA TIN	INDONESIA	CID001460	CFSI			
Gold	Ohio Precious Metals, LLC	Ohio Precious Metals, LLC	UNITED STATES	CID001322	CFSI		Jackson	Ohio
Tin	Xi Hai Liuzhou China Tin Group Cot Ltd	China Tin Group Co., Ltd.	CHINA	CID001070	CFSI			
gold	Metalor USA Refining Corporation	Metalor USA Refining Corporation	UNITED STATES	CID001157	CFSI	255 John L. Dietsch Blvd.	North Attleboro	MA
Tin	Minsur	Minsur	PERU	CID001182	CFSI	AV San Martin 1371	Pisco	Peru
Tin	Yunnan Tin Company, Ltd.	Yunnan Tin Company, Ltd.	CHINA	CID002180	CFSI	32 Beijing Road	Kunming	Yunnan
gold	CCR Refinery – Glencore Canada Corporation	CCR Refinery – Glencore Canada Corporation	CANADA	CID000185	CFSI	100 King Street West	Toronto	Ontario
gold	Republic Metals Corporation	Republic Metals Corporation	UNITED STATES	CID002510	CFSI	12900 NW 38th Ave	Miami	Fla
gold	Royal Canadian Mint	Royal Canadian Mint	CANADA	CID001534	CFSI	320 Sussex Dr.	Ottawa	Ontario
Tin	Gejiu Zi-Li	Gejiu Zi-Li	CHINA	CID000555	CFSI		Gejiu	Yunnan
Tin	Minsur	Minsur	PERU	CID001182	CFSI		Paracas	Ica
Tin	PT Bangka Tin Industry	PT Bangka Tin Industry	INDONESIA	CID001419	CFSI		Sungailiat	Bangka